



Moulded Hardboard


See Reverse for Inventoried Sizes




Colonist Smooth




Carrara Smooth




Caiman Smooth




Santa Fe Smooth




Rockport Smooth




Cremona Smooth




Coventry Smooth




Craftsman III Smooth




Madison Smooth




Monroe Smooth



Conmore Smooth




Colonist Textured




Classique Textured


Wood Doors




F-66




F-44



#730




Divided Lite



1 Lite

MDF Doors by ECCO



E5000

Select a door for more information



Barnett Inventoried Doors

Site	HC Textured Colonist	SC Textured Colonist	HC Smooth Colonist	SC Smooth Colonist	HC Smooth Carrara	SC Smooth Carrara	HC Smooth Caiman	SC Smooth Caiman	HC Smooth Santa Fe	SC Smooth Santa Fe	HC Smooth Rockport	SC Smooth Rockport	HC Smooth Cremona	HC Smooth Coventry	SC Smooth Coventry	HC Textured Classique	HC Smooth Madison	SC Smooth Madison	HC Smooth Monroe	SC Smooth Monroe	HC Smooth Craftsman III	HC Smooth Conmore	F-66	F-44	#730	Wood TDL	Wood 1 Lite	ECCO E5000	HC Flush Lauan	SC Flush Lauan	HC Flush Birch	SC Flush Birch			
1-0 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-4 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-6 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-8 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-10 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-0 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-4 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-6 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-8 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-10 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
3-0 X 6-8	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-3 X 8-0					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-4 X 8-0					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-6 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-8 X 8-0					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-0 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-4 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-6 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-8 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
3-0 X 8-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-6 X 5-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
1-8 X 5-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-0 X 5-0	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-4 X 5-0					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-0 BF (2 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-6 BF (2 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-8 BF (2 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
3-0 BF (2 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
4-0 BF (4 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
5-0 BF (4 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
5-4 BF (4 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
6-0 BF (4 Df.)	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-8 X 6-8 20 Min.	X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
3-0 X 6-8 20 Min.					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
2-8 X 8-0 20 Min.					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X
3-0 X 8-0 20 Min.					X		X		X		X		X		X		X		X		X		X		X		X		X		X		X		X