




## Moulded Hardboard




Colonist  
Smooth




Carrara  
Smooth




Caiman  
Smooth




Santa Fe  
Smooth




Rockport  
Smooth




Classique  
Textured




Craftsman III  
Smooth




Madison  
Smooth



Monroe  
Smooth




Conmore  
Smooth




Colonist  
Textured


## Wood Doors




F-66




F-44



#730




Divided  
Lite




1 Lite


## 1-3/8" Primed Shaker




4020




4102




4103



4103T



4107



4102

## 1-3/4" Primed Shaker

*See Reverse for Inventoried Sizes*



## Barnett Inventoried Doors

Size	HC Textured Colonist	SC Textured Colonist	HC Smooth Colonist	SC Smooth Colonist	HC Smooth Carrara	SC Smooth Carrara	HC Smooth Caiman	SC Smooth Caiman	HC Smooth Santa Fe	SC Smooth Santa Fe	HC Smooth Rockport	SC Smooth Rockport	HC Textured Classique	HC Smooth Madison	SC Smooth Madison	HC Smooth Monroe	SC Smooth Monroe	HC Smooth Craftsman III	HC Smooth Conmore	#4020 1 Panel Shaker	#4102 2 Panel Shaker	#4103 3 Equal Panel Shaker	#4103T 3 Panel Craftsman Shaker	#4107 5 Panel Shaker	#4102 1-3/4 2 Panel Shaker	F-66	F-44	#730	Wood TDL	Wood 1 Lite	HC Flush Lauan	SC Flush Lauan	HC Flush Birch	SC Flush Birch
1-0 X 6-8	x																																	
1-4 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-6 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-8 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-10 X 6-8	x																																	
2-0 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-4 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-6 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-8 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-10 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
3-0 X 6-8	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-3 X 8-0																																		
1-4 X 8-0																																		
1-6 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-8 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-0 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-4 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-6 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-8 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
3-0 X 8-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-6 X 5-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
1-8 X 5-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-0 X 5-0	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-4 X 5-0																																		
2-0 BF (2 Dr.)	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-6 BF (2 Dr.)	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-8 BF (2 Dr.)	x																																	
3-0 BF (2 Dr.)	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
4-0 BF (4 Dr.)	x																																	
5-0 BF (4 Dr.)	x																																	
2-8 X 6-8 20 Min	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
3-0 X 6-8 20 Min	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
2-8 X 8-0 20 Min	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						
3-0 X 8-0 20 Min	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x	x						